

Committee Name: Mousehold Heath Conservators

Committee Date: 17/06/2022

Report Title: Implementation of programme of roofing works

Portfolio: Councillor Giles, Cabinet member for community wellbeing

Report from: Head of environment services

Wards: Catton Grove and Crome

OPEN PUBLIC ITEM

Purpose

To review the programme of roofing maintenance works for the pavilion on Gurney Road.

Recommendation:

To authorise the next stage of roofing works outlined in the works programme to implement the aims and objectives of the management plan.

Policy Framework

The Council has five corporate priorities, which are:

- People live independently and well in a diverse and safe city.
- Norwich is a sustainable and healthy city.
- Norwich has the infrastructure and housing it needs to be a successful city.
- The city has an inclusive economy in which residents have equal opportunity to flourish.
- Norwich City Council is in good shape to serve the city.

This report meets the sustainable and healthy city corporate priority

This report addresses Deliver a Capital Investment Programme in our parks that will improve visitor experience, maintain our heritage assets and improve community cohesion. strategic action in the Corporate Plan

The report helps to meet the Mousehold Heath management plan objective(s):

The report helps to meet the Mousehold Heath management plan objective A and F.

A. To ensure Mousehold Heath is a welcoming place for people to visit.

F. To safeguard the historic landscape, archaeological features and buildings of Mousehold Heath.

Report Details

- 1. The report details the work, activities and issues arising on, and relating to the delivery of the Mousehold Heath management plan objectives.
- 2. The objectives are:
 - A) To ensure Mousehold Heath is a welcoming place for people to visit.
 - B) To protect Mousehold Heath and ensure that it is a safe and secure place to visit.
 - C) To ensure that Mousehold Heath is clean and well maintained.
 - D) To manage Mousehold Heath in a way that has a positive impact on the environment.
 - E) To improve habitats and the natural environment for wildlife to enhance the biodiversity of Mousehold Heath.
 - F) To safeguard the historic landscape, archaeological features and buildings of Mousehold Heath.
 - G) To provide opportunities for local communities to be involved in all aspect of our work.
 - H) To promote Mousehold Heath to increase awareness, knowledge, understanding and a sense of pride.

Pavilion condition survey MC50/06 Ref appendix 1.

Pavilion works programme 2019 to 2025, ref appendix 2.

- 3. The 10 year management plan included maintenance of the pavillion as an asset of the heath, it was the conservators responsibility to maintain it. After a condition survey, a programme of works over a 6 year period was agreed, with extra funding of £6,000.00 per annum income put aside to cover funding.
- 4. The conservators increased their precept by £6,000 for 2019/20 based on the costings for the works identified as being required over the next 6 years and to review the pavilion works programme and budget position to inform a decision on funding allocations for works becoming due in financial year 2022/23.
- 5. It would be prudent to review the budget situation in June 2022, to enable an informed decision to be made on the funding source for works in the pavilion maintenance programme due in financial year 2022/23, taking into account the level of reserves held and the financial impact at the end of financial year 2024/25.
- 6. After discussions with the Civil Engineer (Norse Property Services now Norwich City Council), they had planned the completion of the first stage of the works in 2021/22 and then the second stage in 2022/23.

- 7. However, we were advised to complete both stages of the planned works for 2021/22 and 2022/23 together utilising the procurement of scaffolding just the once, instead of the extra costing that would be incurred to supply this for both stages of works an opportunity to save scaffolding works and costs.
- 8. As highlighted in the original survey, a risk of the continuing escalation in the price of materials may occur as a result of the impact of the pandemic and the war in Ukraine on supply changes.

Consultation

9. None

Implications

Financial and Resources

10. There are no proposals in this report that would reduce or increase resources

Legal

11. Carrying out these works will ensure that the Council continues to meet its statutory obligations with regards to Health and Safety

Statutory Considerations

Consideration	Details of any implications and proposed measures to address:					
Equality and Diversity	None					
Health, Social and Economic Impact	None					
Crime and Disorder	The Mousehold Wardens will continue to work with Norfolk Constabulary to ensure that the Heath is a safe place to visit					
Children and Adults Safeguarding	Safeguarding is a priority for the Mousehold Wardens, and they will continue to signpost vulnerable individuals to the services that they require					
Environmental Impact	None					

Risk Management

Risk	Consequence	Controls Required
Financial	Failure to adequately plan and monitor activities could result in insufficient resources being available to deliver the aims and objectives of the Management Plan for Mousehold Heath	Ensure that sufficient management information is available to continue management and maintenance programme
Operational	Failure to adequately plan and monitor activities could result in insufficient resources being available to deliver the aims and objectives of the Management Plan	Ensure that sufficient management information is available to continue management and maintenance programme
Legal	The Council cannot comply with its legal duty to ensure that buildings are safe for users to access	Ensure that sufficient management information is available to continue management and maintenance programme

Other Options Considered

12. Not carrying out the works

Reasons for the decision/recommendation

13. The recommendation is aimed at gaining authority to carry out the works identified within the report

Background papers: None

Appendices: Project specification and pavilion works programme

Contact Officer: Head of Environment Services

Name: Andy Summers

Telephone number: 01603 987841

Email address: andrewsummers@norwich.gov.uk

Appendix 1.

PROJECT SPECIFICATION

Pro	oject	ref code MC50/06 Proje						oject	title	Pa	Pavilion condition survey										
Bri	ef de	scri	ption																		
То	unde	rtake	a co	nditi	ion s	urve	y of t	he in	terio	r and	exte	rior c	of the	pav	ilion						
Proj lead NH Delivered by NPSN Budget code Budget £s																					
			Ye	ars	activ	ve								Mc	onth	s act	tive				
19/ 20	20/ 21	21/ 22	22/ 23	23/ 24	24/ 25	25/ 26	26/ 27	27/ 28	28/ 29	Α	М	J	J	Α	S	0	N	D	J	F	М
Ap by	Approved by Mousehold Conservators Approval date 15/06/18 //Priority Shouldt												t								
Pro	oject	aims	5																		
	1. 7	o up	date t	he 20) yea	r mai	ntena	ınce p	olan												
Det	tailed	l pro	ject	des	cript	ion															
			ied su enand			o ass	ess th	ne inte	erior	and e	exteric	r con	ditior	n of th	пе ра	vilion	ı to u	odate	the 2	20 yea	ar
Lin	ks to	ado	dition	al ir	nforn	natio	on														

Appendix 2.

Pavilion works programme.

	Option 1 (Revenue only)		2019/20	2020/21	2021/22	2022/23	2023/24	2024/25
ltem	Detail	Condition	Revenue	Revenue	Revenue	Revenue	Revenue	Revenue
		survey	(Budget)	(Budget)	(Budget)	(Budget)	(Budget)	(Budget)
		estimate						
External Chimney	Vertical crack running up length of chimney to rear	£4,000	£4,000					
	elevation. No additional movement apparent since							
	survey of 2016. Investigate and carry out crack							
	stitch repairs. This was previously priced in 2014.							
	Check missing pot is capped appropriately.							
External roof 2	Rear section of main pitched roof has multiple areas	£12,000			£12,000			
	of broken, damaged and slipped tiles. Roof is pin tiles							
	on purlins with no felt or membrane. Recommended							
	removal of tiles, installation of breathable membrane							
	or felt and reinstatement of salvaged tiles, replacing							
	any like for like, as required. Insulate as necessary							
	while ensuring adequate ventilation is maintained.							
External Roof	No insulation to roof. Install additional insulation while	£1,500			£1,500			
Space	maintaining adequate ventilation.							
External	Downpipe section west elevation taped together just	£150	£150					
Rainwater Goods	below roof line. Repair section.							
External Window	Leaded window East elevation 1st floor sections	£2,000	£0					
	cracked /broken. Repair affected sections.							
External Door	Front timber door at low level. Sign of timber rot	£250	£0					
	which may require minor repair only.							
External Pigeon	Pigeons roosting on bays and under eaves area	£2,000			£2,000			
Guano	causing potential environmental hazard, particularly in							
	an area which could be used for eating. Consider							
	external netting and / or pigeon guarding where							
External Rear	appropriate. Timber constructed rear shed with felt roof. Multiple	£1.500			£1.500			
Shed	areas of rot and sections of timber missing. Structure	21,500			21,500			
Sileu	is beyond repair and should be removed. Cost is for							
	removal and make good only.							
External Roof 4	Tomovar and make good only.					£7,500		
Fences and walls							£4,000	
Gates							£500	
External								£18,000
redecorations		Total	£4,150	£0	£17,000	£7,500	£4,500	£18,000
					,	ŕ	,	
		Balance b/f	£8,560	£11,821	£19,232	£9,643	£9,554	£12,465
	Managed unders	Precept	£235,010 £2,500	£235,010 £2,500	£235,010 £2,500	£235,010 £2,500	£235,010 £2.500	£235,010 £2.500
	pena site Raim pavilion budget	£2,500 £1,850	£6,000	£2,500 -£11,000	£2,500 -£1,500	£2,500	-£12,000	
		cast outturn	£1,050		£243,510	_	£231,010	£244,510
	Depreciation adju-		£1,719	£1,719	£1.719	£1,719	£1.719	£1.719
		it charge debit	£2,808	£2,808	£2,808	£2,808	£2,808	£2,808
	1 010011 0010	Balance c/f	£11,821	£19,232	£9,643	£9,554	£12,465	£1,876
			21.,521	2.0,202	,510	,	2.2,.00	2.,010